

The existing properties owners have expressed continued flood impacts, but unfortunately have not kept thorough records of flood damages. However, the owners provided several photos from a flood that occurred on October 11, 2018 that clearly portray the flood impacts as follows:



(A)



(B)

*Figure 1 – Standing in front door of 1953 Franklin Rd. SW facing intersection of Brandon Ave. and Franklin Rd. SW. (A) floodwaters approaching front door and (B) floodwaters begin to enter side door.*



(A)



(B)

*Figure 2 – Standing on sidewalk along Franklin Rd. SW in front of 1953 Franklin Rd. SW facing (A) Brandon Ave./Franklin Rd. SW intersection and (B) northbound Franklin Rd. Floodwaters encroaching on 1941 Franklin Rd. SW can be seen in (B) as water moves off the road to the left of the photograph.*



*Figure 3 – Cleanup of floodwaters and sediment deposition in 1953 Franklin Rd. SW.*